


# ICC Configuration Files Instruction

## 一、ICC curve illustration:


①, Put select ink into designates printer,use adjunct special-purpose software of the ICC American X-Rite Spectrophotometer ,print color block chart , scan the files with the instrument , you can get the ICC configuration files after scanning, (following chart 1)



②,Get ICC configuration files , Use adjunct software ColorShop X of American X-Rite Spectrophotometer,scan the ICC configuration files of the same type of different kind ink, download the files separately, different color line stands for different ink performance , get different inks color gamut comparison chart on the following chart. (eg:following chart 2)

chart 2: **illustration** : we use red stand for file ①, the red line② stand for it color performance on the color gamut .so the same as ③④.

(chart 2)



## 二、ICC Configuration Files Instruction:

1、 Put the ICC Configuration files on the designate computer connect with the printer

C: \WINDOWS\system32\spool\driver\color


(Chart3)



2、 How to download ICC Configuration Files :

①、 open your select chart in the Adobe Photoshop。 (eg:following chart 4 ①)

(chart4)



②、 Then, Click “Image” → “mode ” → “convert into configuration files” (following chart5)

(chart5)




③、 Set the contents on drawing board as follows:( eg:following chart 6)

(Chart 6)




②

④, set ② (foregoing chart 6) as the need downloading ICC files (eg: following chart 7)



⑤, Select the needing ICC files, click "ok", then ICC files has been downloaded into the chart you open. (eg: following chart 8)



⑥、Finished downloading the ICC Configuration files.